

**1. CRUSH HAZARD**

Protective gloves must be worn

Keep hands clear of

- cutting teeth
- moving parts and moving rock

be cautious when

- loading the feed conveyor
- bringing rock up to the veneer gauge
- handling rock

**2. KICKBACK HAZARD**

Stand clear when making each cut

use STOPS on outbound table prior to and during cutting to prevent rock rolling off the outbound table

**3. FLYING DEBRIS HAZARD**

Eye protection must be worn

**4. DUST HAZARD**

Wear appropriate dust mask

**5. NOISE HAZARD**

Ear protection must be worn

**6. ELECTRICAL HAZARD**

Only qualified technicians are allowed to work on the electrical power supply

**7. PRESSURE HAZARD**